

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

## R44

Page 1 of 1

## SERVICE BULLETIN SB-70

**DATE: 25 March 2009** 

TO: R44 Owners, Operators, and Service Centers

SUBJECT: Carbon Monoxide (CO) Detector Retrofit

ROTORCRAFT AFFECTED: R44 Helicopters S/N 0001 thru 1590.

TIME OF COMPLIANCE: Within next 100 flight hours or by 31 July 2009, whichever occurs first.

**BACKGROUND:** Carbon monoxide poisoning can be fatal. This bulletin requires installing CO detectors on helicopters that do not already have a detector.

## **COMPLIANCE PROCEDURE:**

- Determine if caution light labeled "Carbon Monoxide" is installed; if installed, no further action is required.
- If "Carbon Monoxide" caution light is not installed, order KI-164 kit from RHC Customer Service (via RHC web site or by phone). Install per kit instructions. Kit instructions are available online at: www.robinsonheli.com/servelib.htm.

## Approximate Cost:

Parts: \$175 for KI-164 kit if ordered by 31 July 2009.

Order must include helicopter serial number.

Labor: 2 man-hours.