

Pricing for R44 2200-Hour Maintenance & Inspection Performed at RHC

Below pricing for R44 2200-Hour Maintenance and Inspection performed at RHC is effective **15 January 2019**. Base price is for an airworthy R44 properly maintained, undamaged, and without excessive corrosion. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4400 hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes engine 2200-Hour Overhaul performed by RHC or Lycoming and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement of 2200 hours:

Exchange Components

C006 MR Gearbox
C017 Swashplate
C018 Clutch
C021 TR Gearbox
C051 Actuator
D174 Fanwheel
Engine

New Parts

A120 Bellcrank	C169 Muffler
A190 Drive V-Belts	C170 Sheave
C008 TR Assembly	C258 Pitch Links
C016 MR Blades	C274 Windshields
C020 Upper Frame	C667 Skid Shoes
C027 Cooling Panels	C947 & A947 Flex Plates
C121-17 P/P Tube	D079 TR Guard
C005 MR Hub	D224 TR Driveshaft
C158 MR Spindles	C031 TR Pitch Control
C159 Pitch Bearings	C007-5 Fan Shaft & Bearing
	Various small parts & hardware

Base Price for R44 2200-Hour Maintenance & Inspection (does not include upgrades)

R44 Raven I/Cadet (2400-Hours)..... **\$225,000.00 + upgrades**
R44 Raven II..... **\$242,000.00 + upgrades**

UPGRADES

<u>Applicability*</u>	<u>Description</u>	<u>Price</u>
Required thru S/N 0663	Hydraulic Flight Controls (includes pistol grip)	\$47,000.00
Required	KI-163 Full-Flow Oil Filter	\$ 1,050.00
Required	KI-218 Full Throttle Caution Light (see attached for pricing)	
Optional	D575 Pneumatic Front Door Opener	\$ 8,990.00
Optional	C058-8 Cyclic Pistol Grip	\$ 3,850.00
Required	C034 Pop-Out Float Overhaul (includes new floats, covers & cylinder exchange)	\$36,268.00
Required	B900-7 Utility Float Replacement	\$20,800.00
Required	KI-196-1 or -2 Fuel Bladder Tanks	\$ 6,800.00
Required	Camshaft & Valve Train Parts (flat)	\$ 3,303.00
Required	Camshaft & Valve Train Parts (roller)	\$ 9,533.00
Optional, 10001 & subsequent	Air Conditioning	\$20,400.00

*Unless previously installed

Base price also includes:

Complete refurbishing of helicopter interior including new seats (velour), carpet, and headliner. Additional cost for leather seats is \$1,740.00. Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs).

Up-to-date Service Bulletin compliance.

RHC one-year or 1000-hour (whichever occurs first) limited warranty.

Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply. For further information, contact cs1@robinsonheli.com.

KI-218 FULL THROTTLE CAUTION LIGHT UPGRADE

EFFECTIVE 15 JANUARY 2019

R22 SL #66

KI-218-1A \$201.00 If Throttle Bellcrank includes A607-2 Cam
KI-218-1B \$567.00 If Throttle Bellcrank doesn't include A607-2 Cam

R44 Raven SL #52

KI-218-2A \$210.00 If Throttle Bellcrank includes A607-2 Cam
KI-218-2B \$565.00 If Throttle Bellcrank doesn't include A607-2 Cam

R44 Raven II without Air Conditioning

KI-218-3A \$660.00 If Throttle Bellcrank doesn't include A534-1 Stop
KI-218-3B \$240.00 If Throttle Bellcrank includes A534-1 Stop

R44 Raven II with Air Conditioning

KI-218-3C \$210.00